

Special Process: Plating System Assessment, 2nd Edition			
Facility Name:	Elm Plating Company		
Address:	1319 Elm Street		
	Jackson MI 49203		
Phone Number:	517.782.8161	Type(s) of Plating Processing at this Facility:	
Fax Number:	517.782.7758	Process Table A:	
		Zinc	Yes - Chloride Acid Zinc
Number of Plating Employees at this Facility:	213	Zinc Alloy Plating	
Captive Plater (Y/N):	No	Process Table B: Not Applicable	
Commercial Plater (Y/N):	Yes	Mechanical Plating	
Date of Assessment:	5/17/2019	Process Table C: Not Applicable	
Date of Previous Assessment:	5/25/2018	Surface Conditioning of Metals for Decorative Plating or Electropolishing	
		Surface Conditioning of Plastics for Decorative Plating	
Date of Re-assessment (if necessary):			
Previous Years Assessment Dates:	Process Table E: Not Applicable		
May 2018 June 2017, June 2016.	Decorative Plating for Metal and Plastic		
	Process Table F: Not Applicable		
Zinc Alloy Plating Hydrogen Embrittlement Relief Bake	Electropolishing and/or Chrome Flash on Stainless Steel		
Process Hydrogen Embrittlement Relief Bake Process	Process Table G: Not Applicable		
	Hard Chrome Plating		
	Process Table H: Not Applicable		
	Electroless Nickel		
	Process Table I:		
	Hydrogen Embrittlement Relief Bake Process		
	Yes - Per Customer Requirements		
	Process Table J :		
	Process Control and Testing Equipment		
	Yes - Per Customer Requirements		
Current Quality Certification(s):	IATF 16949-2016, ISO 17025- Lab Accreditation, ISO 14001-2015		
Personnel Contacted:			
Name:	Title:	Phone:	Email:
Roberta Hasbrouck	Sales and Marketing	517.782-8161	Roberta.Hasbrouck@elmplating.com
Robert Hunsucker	V. P.Plant Manager	517.782-8161	robert.hunsucker@elmplating.com
Sean Peak	Chemical Engineer	517-782-8161	Sean.Peak@elmplating.com
Clayton Dove	Quality Engineer	517-782-8161	Clayton.Dove@elmplating.com
Brenda Gettings	Director of H.R.	517-782-8161	Brenda.Gettings@elmplating.com
Auditors/Assessors:			
Name:	Company:	Phone:	Email:
Tricia McArthur, Quality Engineer	Elm Plating Company	517-782-8161	Tricia.McArthur@elmplating.com
Bill Dunn, Quality Manager	Elm Plating Company	517-782-8161	Bill.Dunn@elmplating.com
Number of "Not Satisfactory" Findings:	0		
Number of "Needs Immediate Action" Findings:	0		
Number of "Fail" Findings in the Job Audit(s):	0		
Number of Process Table items identified as failed in Comments/Observation column:	0		